



Steven D. Long
Manager
Federal Regulatory

AT&T Services Inc.
1120 20th Street, NW
Suite 1000
Washington, DC 20036

T: 202.457.2047
F: 202.457.3072
steve.long@att.com

May 23, 2007

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street SW
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a)
CC Docket No. 96-98

Dear Ms. Dortch:

AT&T Southeast hereby submits its Notice of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
20070054	Replacing Copper Facilities with Fiber Optic Cable and Digital Loop Carrier Systems	Hopkinsville, Kentucky

This notice is also available at:

http://www.interconnection.bellsouth.com/alerts_and_notifications

If you have any questions, please contact me at (202) 457-2047.

Sincerely,

/s/ Steven D. Long

Attachments

cc: Carmell Weathers

Notice of Network Change – Hopkinsville, Kentucky
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
AT&T Kentucky
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Fourth Quarter, 2007

Location of Changes: Area around intersection of Lafayette Road (Hwy 107S) and Holiday Park in Hopkinsville, Kentucky (including portions of Bahama Dr, Barkley Lake Ct, Bradley Ct, Dale Hollow Dr, Desert Inn Ct, Foston Chapel Rd, Greenbrier Ct, Holiday Park Dr, Lafayette Rd, Las Vegas Dr, Mammoth Cave Ct, Monte Carlo Ct, Nassau Circle, Sands Dr, Sweetbriar Ct, Tanglewood Dr, Treasure Island Ct, and W. 37th St).

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport Plain Old Telephone Service (POTS)-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Terri Bailey 810 Kentucky Ave Paducah, KY 42003 (270) 444-5920
---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the AT&T Southeast Region: **1-888-557-0667**

Outside AT&T Southeast Region: 1-800-786-7619
Fax: 1-205-321-2191

Attachment

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20070054
Issue Date: May 21, 2007